
FLY QUIET SUMMARY



WEEK OF SEPTEMBER 17, 2017 (Week 9)



RUNWAY ROTATION TEST 3 JULY 23, 2017 TO OCTOBER 14, 2017 WEEK OF SEPTEMBER 17TH (WEEK 9)



Fly Quiet Mode ¹										
Time				Operations						
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime ⁴	Primary ⁵	Secondary ⁵	Operations				
9/17/17 - 10:35 PM	9/18/17 - 05:45 AM	7:10	80%	10%	1%	107				
9/18/17 - 10:23 PM	9/19/17 - 05:48 AM	7:25	82%	58%	0%	120				
9/19/17 - 10:11 PM	9/20/17 - 05:38 AM	7:27	83%	4%	0%	103				
9/20/17 - 10:46 PM	9/21/17 - 05:44 AM	6:58	77%	0%	52%	113				
9/21/17 - 10:26 PM	9/22/17 - 05:34 AM	7:08	79%	0%	74%	106				
9/22/17 - 10:32 PM	9/23/17 - 05:48 AM	7:16	81%	46%	21%	105				
9/23/17 - 10:06 PM	9/24/17 - 05:49 AM	7:43	86%	70%	0%	86				
Average (Week of September 17th)										
10:25 PM	5:43 AM	7:18	81%	26%	22%	106				

Rotation Mode ²										
Time				Operations						
Start	Stop	Duration ³ (hrs: mins)	Percentage of Nighttime ⁴	Primary ⁶	Secondary ⁶	Operations				
9/18/17 - 11:26 PM	9/19/17 - 05:30 AM	3:56	44%	81%	0%	54				
9/21/17 - 12:06 AM	9/21/17 - 05:44 AM	4:23	49%	0%	65%	51				
9/21/17 - 10:26 PM	9/22/17 - 03:52 AM	4:06	46%	0%	85%	72				
9/22/17 - 11:36 PM	9/23/17 - 05:39 AM	4:59	55%	90%	0%	52				
9/23/17 - 10:06 PM	9/24/17 - 05:29 AM	6:30	72%	84%	0%	70				
Average (Week of September 17th)										
11:08 PM	5:14 AM	4:46	53%	50%	31%	60				

Notes:

- 1: Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with CDA's Fly Quiet Program.
- 2: Rotation Mode is the period of time in which both arrivals and departures are operating in accordance with the Test.

 Rotation Mode is a subset of Fly Quiet Mode.
- 3: Duration was not continuous because FAR Part 139.
- 4: FAR Part 150 considers nighttime hours 10:00 PM 07:00 AM.
- 5: Percentage of operations on designated runways within Fly Quiet Mode.
- 6: Percentage of operations on designated runways within Rotation Mode.

Comments:

- a: There were 0 requests granted for alternative runways during Fly Quiet Mode.
- b: On the night of 9/17 the Rotation Test was restricted due to FAA flight checks on runways for equipment maintenance and/or testing.
- c: On the night of 9/19 the Rotation Test was restricted due to runway equipment maintenance.

