
FLY QUIET SUMMARY



WEEK OF SEPTEMBER 10, 2017 (Week 8)



RUNWAY ROTATION TEST 3 JULY 23, 2017 TO OCTOBER 14, 2017 WEEK OF SEPTEMBER 10TH (WEEK 7)



Fly Quiet Mode ¹										
Time				Operations						
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime ⁴	Primary ⁵	Secondary ⁵	Operations				
9/10/17 - 10:27 PM	9/11/17 - 05:39 AM	7:12	80%	0%	0%	90				
9/11/17 - 10:15 PM	9/12/17 - 05:44 AM	7:29	83%	1%	61%	111				
9/12/17 - 10:19 PM	9/13/17 - 05:49 AM	7:30	83%	0%	42%	113				
9/13/17 - 10:20 PM	9/14/17 - 05:58 AM	7:38	85%	55%	0%	121				
9/14/17 - 10:27 PM	9/15/17 - 05:44 AM	7:17	81%	69%	0%	126				
9/15/17 - 10:38 PM	9/16/17 - 05:40 AM	7:02	78%	74%	0%	88				
9/16/17 - 10:12 PM	9/17/17 - 05:39 AM	7:27	83%	70%	0%	80				
Average (Week of September 10th)										
10:22 PM	5:44 AM	7:22	82%	38%	16%	104				

Rotation Mode ²										
Time				Operations						
Start	Stop	Duration ³ (hrs: mins)	Percentage of Nighttime ⁴	Primary ⁶	Secondary ⁶	Operations				
9/11/17 - 10:35 PM	9/12/17 - 05:20 AM	5:58	66%	1%	79%	82				
9/12/17 - 11:17 PM	9/13/17 - 05:15 AM	4:55	55%	0%	76%	45				
9/13/17 - 10:20 PM	9/14/17 - 05:29 AM	6:13	69%	60%	0%	106				
9/14/17 - 10:27 PM	9/15/17 - 05:29 AM	6:09	68%	72%	0%	109				
9/15/17 - 10:38 PM	9/16/17 - 05:40 AM	5:57	66%	77%	0%	84				
9/16/17 - 10:12 PM	9/17/17 - 05:39 AM	6:55	77%	74%	0%	76				
Average (Week of September 10th)										
10:34 PM	5:28 AM	6:01	67%	53%	20%	84				

Notes:

- 1: Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with CDA's Fly Quiet Program.
- 2: Rotation Mode is the period of time in which both arrivals and departures are operating in accordance with the Test.

 Rotation Mode is a subset of Fly Quiet Mode.
- 3: Duration was not continuous because FAR Part 139.
- 4: FAR Part 150 considers nighttime hours 10:00 PM 07:00 AM.
- 5: Percentage of operations on designated runways within Fly Quiet Mode.
- 6: Percentage of operations on designated runways within Rotation Mode.

Comments:

- a: There was 1 request granted for alternative runways during Fly Quiet Mode.
- b: On the night of 9/10 the Rotation Test was restricted due to runway equipment maintenance.

